

0151328

19 JUN 1963

1963 JUN 19 04 30Z

PRIORITY

P 190327Z

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUWGAA/HQS 2ND AF BARKSDALE, LA

RUWGSN/4080TH SRW, LAUGHLIN AFB, TEXAS

DA GRNC

BT

S E C R E T

CITE CIA-Z-687

FOR DI, BRASS KNOB, DOCR, DM 4, DIM, SAC HQS, OMAHA. FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER. SUBJECT: FILM EVALUATION MISSION 3632.

1. CAMERA B 13 WAS USED IN MISSION 3632 FLOWN ON 16 JUNE 63; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.
2. ORIGINAL NEGATIVE: THE RESOLUTION IS GOOD AND THE EXPOSURE IS ADEQUATE.
3. 9R SIDE: A VERY FINE PLUS DENSITY STREAK, 3.2 INCHES IN FROM THE OUTBOARD EDGE, OCCURS INTERMITTENTLY THROUGHOUT THE MISSION. A SMALL TRIANGULAR SHAPED OBSTRUCTION IS PRESENT, ADJACENT TO THE DATA CHAMBER, IN THE 2R POSITION. A VERY SLIGHT EDGE FOG OCCURS INTERMITTENTLY ALONG THE OUTBOARD EDGE OF THE FILM. A LONG HEAVY SCRATCH IS PRESENT ON THE EMULSION SIDE OF FRAME 1476.
4. 9L SIDE: PLUS DENSITY MARKS, POSSIBLE DUE TO STATIC

HFS

CS

AC

CFC

FILE

Declassification Review by NGA/DoD

SECRET

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

ASSOCIATED WITH THE CAMERA PRESSURE ROLLER OCCURS ALONG THE INBOARD EDGE OF FRAMES 1 TO 129. STATIC IS CONTINUOUS ALONG BOTH FILM EDGES THROUGH FRAME 50, THEN BECOMING INTERMITTENT FOR THE REST OF THE MISSION. A SLIGHT FOG IS PRESENT INTERMITTENTLY ALONG BOTH FILM EDGES THROUGHOUT.

5. NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS WERE NOTED ON THIS MISSION.

6. POSITIVE: PI SUITABILITY IS GOOD WHERE WEATHER DOES NOT DEGRADE IMAGERY. CLOUD COVER IS APPROXIMATELY 40 PERCENT.

7. NO PRINTING OR PROCESSING PROBLEMS WERE ENCOUNTERED.

SCP-1

S E C R E T

END OF MESSAGE

(SIG CEN NOTE: ABOVE MSG ALSO TRANSMITTED CIA WATHC ASP/RR)